

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,917,875 B2
DATED : July 12, 2005
INVENTOR(S) : Dale R. Boysen et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 7.


Line 60, please replace "port" with -- ports --;
Line 61, please insert -- a -- before "transducer";

Column 8.

Line 12, please replace "port" with -- ports --.

Signed and Sealed this

Sixth Day of September, 2005



JON W. DUDAS
Director of the United States Patent and Trademark Office